




d _{G6}		T	D _{m5}		H	ℓ																							
						L15	L20	L25	L30	L35	L40	L45	L50	L60	L70	L80	L90	L100	L110	L120	L130	L140	L150						
8	+0.014	5	12	+0.015 +0.007	14	15	15	15	—	—	—	—	—	—	—	—	—	—	—	—	—	—							
10	+0.005		14		16	15	20	20	20	20	20	—	—	—	—	—	—	—	—	—			—						
12	+0.017 +0.006		18		22	15	20	25	25	25	25	25	25											—	—	—	—	—	—
13			20	25	15	20	25	25	25	25	25	25	25																
16	+0.020 +0.007	6	25	+0.017 +0.008	30	15	20	25	30	35	30	30	—	—	—	—	—	—	—	—	—	—							
20		30	35		—	20	25	30	35	40	40	40											40	40	40	40	40	40	40
25		8	35	+0.020 +0.009		40	—	20	—	30	35	40	45	50	50	50	50	50	50	50	50	—	—						
28			40		—	25		30	35	40	45	50	56	56	56	—	—	—	—	—									
30			42			25		30	35	40	45	50	60	60	60	60	60	60	60	60									
32			45			25		30	35	40	45	50	60	60	60	60	60	60	60	60									
35		+0.025 +0.009	10	48	+0.024 +0.011	54	—	—	—	30	35	40	—	50	60	70	70	70	70	70	70	—	—						
36				50		30				35	40	—	50	60	70	—	—	—	—	—	—								
40	55			30		35				40	45	50	60	70	80	80	80	80	80	80									
50	70			—		—				40	45	50	60	70	80	90	100	100	100	100	100			100	100				
60	+0.029 +0.010	12	80		86				—	—	—	60	70	80	90	100	110	120	120	120	120	120							



Order

Part Number — L
GBHE13 — 40